



**ACHTUNG!**  
**ATTENTION!**

The warning diagram shows a locomotive with a sad face and lightning bolts around it, indicating a problem. A transformer is shown with a red 'X' over it, and a DC power source is shown with a red arrow pointing to it. The text 'Wechselstrom' and 'AC Courant alternatif' is crossed out with a red 'X'. The text 'Gleichstrom DC Courant continu' is shown with a red arrow pointing to it. The Märklin logo and '6700-6739' are also present.

Die Lokomotive ist mit Funk-Entstörmitteln ausgestattet, die im Zusammenwirken mit den in den Märklin-Transformatoren 6711 bzw. 6731 und im Anschlußgleisstück 8590 eingebauten Störschutzelementen das Einhalten der Bestimmungen von VDE 0875 gewährleisten.

Sollten beim Betrieb der Spielzeuganlage, z. B. wegen zu geringem Abstand gegenüber der Empfangsantenne oder bei Abweichungen vom vorgegebenen Aufbau der Verkaufspackung, Funkstörungen auftreten, so ist die Störung sofort, z. B. durch Aufstellen der Anlage an einem anderen Ort oder durch Ändern des Aufbaues, zu beseitigen.

**märklin mini-club**

Printed in Western Germany  
Imprimé en Allemagne

**märklin mini-club**

**8842/8855**

68673 TN 0179 ju

Nach 20 Betriebsstunden  
After 20 h service

